

TITLE	Lens Thermal Cold Test
DOCUMENT TYPE	REPORT
DOC No.	AMST/CTVL/1/A
ISSUE No.	1
DATE	19/07/06



Prepared by:	ANDREA BUCCONI	(CARSO)	
Approved by:	PAOLO TRAMPUS	(CARSO)	

Table of Contents


1. Visual inspection 5


2. Spot acquisition 7

List of Tables

1. Visual inspection

After the test an accurate visual inspection was performed on lens and filters. No damage was noticed. In the next two pictures taken after the test, the lens assembly is shown.





2. Spot acquisition

A spot generated by a laser and the beam expander was acquired. In the following figures the spot acquired image and a 3D graph of the spot are given.





Image of the spot



3D visualization of the spot